



THE GILL CORPORATION

HIGH PERFORMANCE COMPOSITE PRODUCTS SINCE 1945

CASTLE INDUSTRIES INC OF CALIFORNIA
COMPONENT MAINTENANCE MANUAL,
SERVICE BULLETIN AND OVERHAUL MANUAL INDEX
2/21/17

THE DATA BELOW IS CONSIDERED CURRENT AND IS UPDATED WHEN THERE IS ANY CHANGE IN REVISION LEVEL. SHOULD YOU HAVE ANY QUESTIONS REGARDING THIS INFORMATION, PLEASE EMAIL INFO@CASTLEINDUSTRIES.NET

| Document | ID | Rev | Date | Part Number |
|------------------|--------------|-----|----------|--|
| CMM | 25-11-01 | 5 | Jun-2014 | 0801801-1, -2, -3, -4,-5,-6,-7,-8,-9,-10,-11,-12 |
| CMM | 25-11-02 | N/C | Sep-1985 | 11-007-1 |
| CMM | 25-11-04 | N/C | Mar-2016 | 17-001-1 |
| CMM | 25-11-05 | N/C | Jan-1993 | 18-001 |
| 0801801-25-1 SB | 0801801-25-1 | N/C | Jan-1983 | 0801801-1,-2,-4 |
| 0801801-25-2 SB | 0801801-25-2 | N/C | Nov-1984 | 0801801-1, -2, -3, -4 , -5, -6, -7, -8 |
| 0801801-25-3 SB | 0801801-25-3 | 1 | Mar-1986 | 0801801-2, -4, -9, 10, -11 and 0801801-7, -12 |
| 08-036 SB | 08-036 | N/C | Aug-1999 | 0801801-1, -2, -3, -4,-5,-6,-7,-8,-9,-10,-11,-12 |
| Overhaul Manual | 25-1-1 | B | Jul-2015 | 50103-500 thru 505 and 50104-500 through 505 |
| 50103-04-25-2 SB | 50103/4-25-2 | N/C | Apr-1986 | 50103-() and 50104-() |